




BUILDING B – NO CHANGE TO EXTERIOR
FRONT ELEVATION (SOUTH)



BUILDING B – NO CHANGE TO EXT.
RIGHT SIDE ELEVATION (EAST)



BUILDING B – NO CHANGE TO EXTERIOR
REAR ELEVATION (NORTH)




BUILDING C – NO CHANGE TO EXTERIOR
FRONT ELEVATION (SOUTH)



BUILDING C – NO CHANGE TO EXTERIOR
REAR ELEVATION (NORTH)




BUILDING D – NO CHANGE TO EXTERIOR
FRONT ELEVATION (SOUTH)



BUILDING D – NO CHANGE TO EXT.
LEFT SIDE ELEVATION (WEST)



BUILDING D – NO CHANGE TO EXTERIOR
REAR ELEVATION (NORTH)




BUILDING E – NO CHANGE TO EXT.
LEFT SIDE ELEVATION (NORTH)



BUILDING E – NO CHANGE TO EXTERIOR
FRONT ELEVATION (EAST)



BUILDING E – NO CHANGE TO EXTERIOR
REAR ELEVATION (WEST)



BUILDING E – NO CHANGE TO EXT.
RIGHT SIDE ELEVATION (SOUTH)